



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit [www.iecex.com](http://www.iecex.com)

|   |  |   |
|---|--|---|
| QAR Ref. No.:                               | <b>GB/CML/QAR19.0001/08</b>  | Page 1 of 1   |
| QAR Free Ref. No.:                          | <b>R17599A/00</b>  | Status: <b>Issued</b>   |
| Details of change:                          | Reassessment Audit at British Engines site   | Date of issue: <b>2024-09-05</b>                                    |
| Location(s) audited:                        | <b>British Engines (India) Pvt. Ltd</b><br>6A Attibelle Industrial Area<br>Bangalore 562107<br><b>India</b>      | Valid until: <b>2027-08-29</b><br><br>Audit date: <b>2024-08-14</b> |
| Issuing ExCB:                               | <b>CML - Eurofins E&amp;E CML Limited</b>  |   |
| Manufacturer:                               | <b>CMP Products Limited</b><br>36 Nelson Way<br>Nelson Park Way<br>Cramlington NE23 1WH                          |   |
| Location of Manufacturer:                   | <b>United Kingdom</b>  |   |
| Product information:                        | Cable glands and accessories   |   |
| Type of protection:                         | <b>CMP Products Ltd Ex d, e, t, nR British Engines (India) Pvt. Ltd Ex d, e, t, Trace Heating IEC 60079-30-1</b> |   |
| Related QARs:                               |  |   |
| GB/CML/QAR19.0001/00                        | GB/CML/QAR19.0001/01   | GB/CML/QAR19.0001/02  |
| GB/CML/QAR19.0001/03                        | GB/CML/QAR19.0001/04   | GB/CML/QAR19.0001/05  |
| GB/CML/QAR19.0001/06                        | GB/CML/QAR19.0001/07   |   |
| Related Certificates (manual insertion)::   |  |   |
| Related Certificates (automatic linking)::  |  |   |
| Related Certificates for previous versions: |  |   |
| IECEX CML 18.0171U issue: 1                 | IECEX CML 18.0171U issue: 2  | IECEX CML 18.0172 issue: 0  |
| IECEX CML 18.0172 issue: 1                  | IECEX CML 18.0173X issue: 0  | IECEX CML 18.0174 issue: 0  |
| IECEX CML 18.0175X issue: 0                 | IECEX CML 18.0176U issue: 0  | IECEX CML 18.0177X issue: 0   |
| IECEX CML 18.0177X issue: 1                 | IECEX CML 18.0177X issue: 2  | IECEX CML 18.0178X issue: 0   |
| IECEX CML 18.0178X issue: 1                 | IECEX CML 18.0179X issue: 0  | IECEX CML 18.0179X issue: 1   |
| IECEX CML 18.0179X issue: 2                 | IECEX CML 18.0180X issue: 0  | IECEX CML 18.0181X issue: 0   |
| IECEX CML 18.0181X issue: 1                 | IECEX CML 18.0182X issue: 0  | IECEX CML 18.0182X issue: 1   |
| IECEX CML 18.0183X issue: 0                 | IECEX CML 18.0184X issue: 0  | IECEX CML 18.0185U issue: 0   |
| IECEX CML 18.0186U issue: 0                 | IECEX CML 18.0186U issue: 1  | IECEX CML 18.0187U issue: 0   |
| IECEX CML 18.0188U issue: 0                 | IECEX CML 18.0189U issue: 0  | IECEX CML 18.0190X issue: 0   |
| IECEX CML 18.0190X issue: 1                 | IECEX CML 18.0191X issue: 0  | IECEX CML 18.0192X issue: 0   |
| IECEX CML 18.0193X issue: 0                 | IECEX CML 19.0062X issue: 0  | IECEX CML 19.0062X issue: 1   |
| IECEX CML 19.0062X issue: 2                 | IECEX CML 19.0062X issue: 3  | IECEX CML 19.0062X issue: 4   |
| IECEX CML 20.0038X issue: 0                 | IECEX SIM 15.0002X issue: 1  | IECEX SIM 17.0009U issue: 1   |
| IECEX SIM 17.0010 issue: 1                  |  |   |
| Comments:                                   |  |   |